

**Appendix-A****Details of AC's, Water cooler and Fridge in NCRB as on 08.02.2016**

Sl. No.	Location	Capacity (in ton)	Make	Sl. No.	date of purchase	Cost in Rs.
1	DG, NCRB	1.5	Blue Stat(HC)	WAM046214	19.02.2005	17000
2	DG, NCRB	2.0	Voltas(Split)	4510942P09E000025	09.06.2009	21686
3	DG, NCRB	2.0	Voltas(Split)	45509960U08e961263	18.06.2009	21686
4.	PS to DG, NCRB	1.0	Hitachi (W)		04.07.2012	26000
5	JD(Admn.)	1.5	Hitachi(Split)	RASU023HQDG	16.03.2011	21200
6.	JD(CCTNS-I)	1.5	Voltas(Split)	4550989P09H000201	31.08.2009	32780
7.	JD(CCTNS-II)	1.5	Hitachi(Split)	SE100H02572	17.07.2010	24627
8.	DD(Adm)	1.5	Hitachi(Split)	SE100H02574	17.07.2010	24627
9	DD(CCTNS)	1.5	Fedders Lloy/W	SW045E20000124	29.05.2000	22408
10	AD(Adm.)	1.5	Purison	RC544	27.03.1996	18300
11	PS to JD(A&CCTNS)	1.5	Blue Star(HC)W	WAM181Y047871	28.03.2005	17000
12.	JAD(G)	1.5	Purison	RC543	27.03.1996	18300
13.	Director I/c CFPB	1.5	Fedder Lloyd	SW045H990286	09.09.1999	22408
14	AD(R)	1.5	Voltas (W)	4010070U08M507528	08.06.2009	28879
15.	CSO	1.5	Voltas/ W	4010070U08m507453	08.06.2009	28879
16	SO(Stat)	1.5	Blue Star/W	Not read able	31.10.2005	1800
17	Admn.IB	1.0	Hitachi /W		04.07.2012	26000
18	Dy. S. CPF	1.5	Fedder Llooyd	SW045E20000122	29.05.2000	22408
19	Admn.II	2.0	Blue Star/W	RC241RC024020043	31.07.2002	21500
20	AD.IA	2.0	Voltas/W	475	22.08.2003	21500
21.	Account Section	2.0	Voltas/W	485	22.08.2003	21500
22.	Casher	2.0	Voltas/W	483	22.08.2003	21500
23.	Reception	1.0	Hitachi/W		04.07.2012	26000
24.	C.R. Hall	2.0	Blue Star/W	RC241RC024020041	31.07.2002	21500
25.	C.R. Hall	2.0	Blue Star/W	RC241RC024020042	31.07.2002	21500
26.	C.R. Hall	2.0	Blue Star/HC/W	WAM241R050970	31.10.2005	14978
27	C.R. Hall	2.0	Blue Star/HC/W	WAM241R050922	31.10.2005	14978
28	C.R. Computer Room	2.0	Voltas/W	480	22.08.2003	21500
29	Conference Hall	1.5	Hitachi(Split)	RAU018HQDG	24.11 2010	24627
30	Conference Hall	1.5	hitachi(Split)	RAU023HQDG	24.11.2010	24627
31	Conference Hall	2.0	Hitachi (Split)	RAU023HQDG	24.11.2010	25247
32.	Library	1.5	Vedeocon	11085072003208	26.08.2005	14090
33.	CFPB Insp. Room	2.0	Voltas/W	4010051P09E000044	08.06.2009	16607
34.	CFPB Insp. Room	2.0	Hitachi/W	FAV024EQDG/2011	16.03.2011	27840
35	CCTNS Workshop	1.5.	Blue Star/HC	WAM181Y045965	16.03.2005	17000
36.	CCTNS Workshop	1.5	Blue Star/HC	WAM181y047971	16.03.2005	17000
37..	CCTNS Workshop	1.5	Hair	Not readable	08.05.2009	
38	Vehicle NOC Counter	2.0	Voltas	4010051P09E000002	08.06.2009	16607
39	Stat. Computer Room	2.0	Voltas	4010051P9E000037	08.07.2009	21686
40	CR/Stat	2.0	Voltas(Split)	4510942P09H000245	31.08.2009	38140
41	DCT Branch	2.0	Hitachi/Split	SE100G07919	30.06.2010	33654
42.	DCT Branch	2.0	Hitachi/Split	SE100G07912	30.06.2010	33654
43.	DCT Branch	2.0	Hitachi/Split	SE100G07913	30.06.2010	33654
44.	CCTNS Lab	1.5	Blue Star /W	Not readable	31.10.2005	18000
45	CCTNS Workshop	1.5	Blue Star / W	WAM181Y045965	16.03.2005	17000
46.	CCTNS Workshop	1.5	Blue Star/W	WAM181Y047971	16.03.2005	17000
47	Trg Room Basement	1.5	Blue STar/W	WAM046214	19.02.2005	17000
48.	Meeting Hall Basement	1.5	Blue Star/W	WAM181y046182	19.02.2005	17000

49	Meeting Hall Basement	1.5	Blue Star/W	WAM181Y047965	19.02.2005	17000
50	CCTNS Basement	1.5.	Blue Star/W	WAM181y04544519.	19.02.2005	17000
51.	CCTNS Basement	1.5	Blue Star/W	WAm181Y045263	19.02.2005	17000
52.	Trg. Class room E.B.7	1.5	Panasonic/Split	2484735042	03.05.2012	24500
53.	Trg. Class room, E.B.-7	1.5	Panasonic/ Split	2484734614	03.05.2012	24500
54	JAD(Trg.)	1.0	Panasonic/Split		03.05.2012	20500
55	Store	1.5	Hitachi/W	RAV024EQDG		
56	JD(CCTNS-II)	1.0	Blue Star		13.09.2013	20500
57	DCT Branch	2.0	Blue Star		26.06.2014	40190
58	<b>FRIDGE</b>					
59	DG, Office	251 Ltr.	Samsung			
60	Trg. Branch	251 Ltr	Godrej			
61	Canteen	280 ltr.	Samsung			
	<b>Water Cooler</b>					
62	East Block-7	1.05 ltr.	Blue Star		29.03.2005	35000
64	<b>DISPENSERS</b>					
	East Block-7 & 9	14 , with Fridger	Voltas			